



MAX 40



Poweron - Plasma Plus.

PCH-51



- 1. O-RING 969003-010
- 2. ELECTRODE 969003-011
- 3. TIP 969003-012
- 4. SHIELD CUP 969003-013
- 5. CASTLE CUP 969003-014
- 6. NUT DRIVER 969003-016
- 7. TIP WRENCH 969003-017